



**Post Clean Verification Report No:
CRM Number**

Client

At

Building No1

System Name



INDEX

	<u>Section</u>
Preface	1
Introduction	2
Frequency of Cleaning	3
Executive Summary	4
Description of System	5
Pre & Post-Clean WFTT Results	6
Photographic Evidence	7
Additional Photos	8
Schematic Drawing	9
Certificate	10

Section 1: Preface

Customer:	Customer
Site Address:	Building No1
Hydro-X Account Manager:	Account Manager
Account Manager Telephone Number:	0123456789
Account Manager Email Address:	Account.Manager@hydro-x.co.uk
Hydro-X Address:	Hydro-X Air Ltd The Maylands Building Maylands Avenue Hemel Hempstead HP2 7TG
Hydro-X Telephone Number:	01909 565133
Hydro-X Email Address:	info@hydro-x.co.uk
Hydro-X Operatives Carrying Out Works:	Site personnel names
Date of Assessment:	Date

Any further information concerning this assessment should be requested by contacting the above-named Hydro-X Account Manager

Section 2: Introduction

Kitchen Extract Cleaning Standards

Extract from **TR19® Grease Specification - Section 8 - Table 6: Surface Grease Deposit Limits** sets out guideline maximum levels of grease deposit and actions recommended. The actual recommended action timing will depend on the rate of accumulation, the risk vulnerability of the system and site and any particular conditions imposed by the property insurers.

Table 6:

Wet Film Thickness Test Measurement	Recommended Action
200µm as a mean across the system	Complete cleaning required
Any single measurement above 500µm	Urgent local cleaning required (notes 4 & 5)

Notes to Table 6:

1. The deposit limits refer to the degree of grease deposition within the ductwork consistent with good practice. Other factors such as cooking methods, cuisine, potential ignition sources, and other combustible debris will affect the risk of fire.
2. The mean measurement is calculated by dividing the total of the test results by the number of testing locations.
3. The second category of any single measurement above 500µm is provided to cater for local "hot spots" which should be cleaned even where the whole system does not require complete cleaning. Examples might be immediately local to a canopy or at a fan.
4. The extent of urgent local cleaning required by the presence of grease deposits above 500µm shall be subject to reasonable appreciation of the extent of fouling and risk posed.
5. The surface grease deposits limit should not be confused with the level set for post-clean verification which is far more stringent. (See section 6).
6. Where remote cleaning methods have been used in areas where WFTT measurements would not be possible, then visual assessment shall be used and that this would be achieved by remote camera or video support.

Section 3: Frequency of Cleaning:

(TR19® – Grease Specification for Fire Risk Management of Grease Accumulation within Kitchen Extraction Systems)

Section 5. Frequency of cleaning - control of grease and fire risk

5.1 Unless recommended otherwise in a fire risk assessment undertaken by the client's responsible person, all operational grease extract ductwork systems will usually require cleaning annually as a minimum.

5.2 Specific cleaning intervals stated by landlords, system designers or insurers should be identified by the owner/operator and notified to the cleaning and maintenance contractor.

5.3 Conditions and warranties within commercial liability/property insurance policies, should stipulate minimum cleaning frequencies for grease extract ductwork systems. However, some insurance contracts may require a higher frequency of cleaning than recommended in TR19®. Failure to comply with such requirements may invalidate the property insurance policy.

5.4 The frequency of cleaning should be sufficient to ensure that grease deposit limits of 200µm, as a mean across the system, are not exceeded.

Table 3: Grease Deposit Thickness Limits

Wet Film Thickness Test Measurement	Recommended Action
200µm as a mean across the system	Complete cleaning required
Any single measurement above 500µm	Urgent localised cleaning required to area

5.5 All cleaning frequencies should be based upon accurate historical levels of grease accumulation to maintain grease deposit levels below 200 microns as a mean across the system.

5.6 In certain cases sections of ducting may accumulate grease levels over 500 microns, often referred to as 'hot spots' or 'high points'. Such areas should be cleaned urgently with the caveat that the extent of fouling at 500 microns and the level of risk posed should be considered. For example, 500 microns within the canopy plenum, immediately above the heat source would be a far higher risk than a small high point on a turning vane many meters away from the heat source. Interim cleaning of such high point areas should be introduced to the full system cleaning schedule where it is agreed that this is required to control the risk of high point grease level accumulation.

5.7 In the absence of data for historic grease deposit levels, such as a newly installed systems, time-and-usage-based methods can be used to estimate required initial cleaning frequency (see Table 4). Pre-cleaning micron readings and time periods between cleaning should be taken to accurately determine ongoing cleaning frequency so that grease levels are maintained below 200 microns as a mean across the system.

5.8 Table 4 will assist in establishing the initial cleaning frequency for the system in the absence of data on the historical pre-clean grease thickness levels and duration of days between each set of grease thickness readings.

Table 4 Initial Clean Frequency Calculator.

Perceived level of grease production	Typical example	Cleaning intervals (months) Daily usage			
		Up to 6 hours	6–12 hours	12-16 hours	16+ hours
Low	No significant production of grease laden aerosols during normal daily food production operations	12	12	6	6
Medium	Moderate production of grease laden aerosols during normal daily food production operations	12	6	4	3
High	Heavy, significant, or continual production of grease laden aerosols during normal daily food production operations	6	3	3	2

Notes to Table 4

1. The canopy and extract plenum are areas with a high risk of fire. Consideration should be given to more frequent cleaning in accordance with insurers' requirements.
2. In addition to the scheduled specialist cleaning, a daily or weekly cleaning regime should be implemented on canopies, separators and associated drain and traps in accordance with manufacturers' recommendations. Typically, these are carried out by the kitchen operator to comply with the property insurers' requirements.

5.9 Predictive Accumulation Assessment Table:

In order to quickly assist in selection of the correct cleaning intervals Table 5 assesses the required cleaning intervals against average grease accumulation that has built up over a number of days.

Table 5 - Frequency of grease risk control clean vs average daily grease accumulation

Frequency of Control Clean	Daily Micron Average Accumulation Range
Twice weekly	28.7 upwards
Weekly cleaning	14.4 to 28.6
Every 2 weeks	9.6 to 14.3
Every 3 weeks	6.7 to 9.5
Monthly	4.8 to 6.6
Every 6 weeks	3.3 to 4.7
Every 2 months	2.2 to 3.2
Quarterly	1.7 to 2.1
Every 4 months	1.1 to 1.6
Every 6 months	0.6 to 1.0
Annually	0.5 or less

Notes to Table 5

1. The frequency guidance table requires a simple calculation to define daily rate of accumulation in microns.
2. To calculate daily rate, take mean pre-clean system micron levels and divide by number of days since previous clean or opening of site and grease production.
3. Select appropriate range to define the frequency of the risk control clean required to ensure micron levels do not exceed 200 as a mean between each cleaning visit.
4. It should be noted that cleaning frequencies shown in Table 5 are indicative only and are based on historic usage of the system. They should not be seen as substitutes to an actual cleanliness risk assessment undertaken by a competent person. When calculating the cleaning frequency seasonal variations and changes in the type and frequency of cooking should be taken into consideration. An additional risk assessment may be required as a result.

Should you require any evidence or substantiating information on any of the above, please do not hesitate to speak to your individual Account Manager, or contact us via one of the following means:



01923 262776



info@hydro-x.co.uk



www.hydro-x.co.uk

Section 4:Executive Summary

The kitchen extract system was found in good physical condition, with a low level of grease deposits throughout the system.

Kitchen extract system cleaning including canopy, canopy plenum, grease separators, drip trays, riser, fan unit, discharge, and all accessible associated ductwork completed up to TR19® – Grease Specification for Fire Risk Management of Grease Accumulation within Kitchen Extraction Systems.

A detailed description of the system can be found on the next page and is also highlighted on the schematic diagram.

Hydro-X Air

Section 5: Description of System

Has the complete system been fully cleaned? (including canopy, ductwork, fan, discharge):	Yes
If No to above, reason why and ways to achieve system full clean:	N/A
Do additional access doors need to be fitted? (Yes/No, if yes what size & how many)	Yes 2x450x450
Current Cleaning Frequency:	6 Monthly
Recommended new frequency of cleaning? (based on micron readings)	3 Monthly
No. of Canopies:	1
Canopy Size (Length & Width):	6 X 3
Canopy Visual Condition:	Satisfactory
No of Grease Separators:	12
Grease Separator Type:	Baffle
Grease Separator Condition:	Satisfactory
Ductwork Shape:	Rectangular
Ductwork Type:	Galvanized
Ductwork Condition:	Poor Condition
Fan Condition & Accessibility:	Fan unit in good condition with high level of grease deposits. Fully accessible.

Section 6:Pre & Post-clean Wet Film Thickness Test Results

	Test Location	Pre-Clean Wet Film Thickness in microns	Post-Clean Wet Film Thickness in microns
1	Canopy / extract plenum (WFTT 1)	300	<50
2	Duct, 1M from canopy (WFTT 2)	800	<50
3	Duct, 3M from canopy (WFTT 3)	800	<50
4	Duct, midway between canopy and fan (WFTT 4)	700	<50
5.	Duct, upstream of fan (WFTT 5)	700	<50
6	Duct, downstream of fan (WFTT 6)	700	<50
The average micron reading across system		667	<50

Section 7: Photographic Evidence

Canopy Hood pre-clean:



Canopy Hood post-clean:



Canopy plenum Pre-clean:



Canopy plenum Post-clean:



Header Duct pre-clean:



Header Duct post-clean:




Duct 1m from Canopy pre-clean:




Duct 1m from Canopy post-clean:



Extract fan/discharge pre-clean:



Extract fan/discharge pre-clean:



Section 8: Additional Photographs

2000+ microns in Header Duct



2000+ on wall of Ducting



The drawing shows all accessible ductwork under pressure. Where pipe runs cannot be verified there have been attempts at positive flow.

LEGEND:

- ▲ RISER
- CLEAN DUCT
- UNABLE TO CLEAN DUCT
- AD - ACCESS DOOR
- FAN

100131-HX-A-001



CERTIFICATE OF CLEANING

This is to certify the kitchen extract system at the site named below has been cleaned in accordance with BESA TR19® Grease Specification for Fire Risk Management of Grease Accumulation within Kitchen Extraction Systems July 2019.

Report Reference Number: CRM Number

Customer: Customer

Site: Site Name
Site Address

System Details: System Details

Date: Date

The internal surfaces of the kitchen extract systems including the accessible ductwork and extract fan to exhaust were cleaned using approved methodologies as stated in BESA TR19® Grease Specification for Fire Risk Management of Grease Accumulation within Kitchen Extraction Systems July 2019.

Hydro-X Air: Signature

Print Name: Site Operative

Hydro-X Air Ltd, The Maylands Building, Maylands Avenue, Hemel Hempstead, HP2 7TG

