Rycho-X Air

NO. =	NEW REF. - NO.	ROOM NUMBER =	AREA 👳		TYPE =	LAST TEST = RESULT		DATE TESTED =		NEW TEST - RESULT	ACCESS HATCH T	ADDITIONNAL HATCH FITTED	ADDITIONNAL COMMENT 1	ADDITIONNAL COMMENT 2	ADDITIONNAL COMMENT 3	ADDITIONNAL COMMENT 4			
992	521	HR-07-10-326	D10	Riser cupboard next to lift	LINK	Not Found	Mechanical Damper	4/11/2019	1010521	Fail 🔻	Yes	No	Fire Damper Not Sealed In Fire Compartment	· -	•		Motorised Damper	Pass	Yes
	522	HR-07-10-326	D10	Riser cupboard next to lift			Mechanical 🚽 Damper	4/11/2019	1010522	Fail 🔻	No	No	Fire Damper Not Sealed In Fire Compartment	· •	-		Mechanical Damper	Fail	No
	523	HR-07-10-326	D10	Riser cupboard next to lift			Mechanical - Damper -	4/11/2019	1010523	Fail 🔻	No	Unknown	Fire Damper Not Sealed In Fire Compartment	· -	-		Advanced Air Damper	Not Found	Unknown
	524	HR-07-10-326	D10	Riser cupboard next to lift			Mechanical - Damper -	4/11/2019	1010524	Pass 👻	Yes	No	Ductwork Requires - Cleaning	Fire Damper Not Sealed In Fire + Compartment	-				
993	525	HR-07-10-305	D10	ENTRANCE	LINK	Not Found	Mechanical - Damper -	4/11/2019	1010525	Fail 🔫	Yes	No	Fire Damper Not Sealed In Fire Compartment	Ductwork Requires Cleaning	-				
	526	HR-07-10-332	C10	Entrance to ward C10			Mechanical Damper	4/11/2019	1010526	Fail 🝷	Yes	- Unknown -	Fire Damper Not Sealed In Fire Compartment	-	-				
	527	HR-07-10-327	C10	Entrance to ward C10 store 1			Mechanical - Damper	4/11/2019	1010527	Fail 🝷	Yes	- Unknown -	Ductwork Requires Cleaning	-	-				
995	528	HR-07-10-327	C10	STORE 1 IN ENTRANCE	LINK	PASS	Mechanical Damper	4/11/2019	1010528	Pass *	Yes	No		· -	-				
999	529	HR-07-10-101	C10	C 10 CORRIDOR	LINK	PASS	Mechanical Damper	4/11/2019	1010529	Pass -	Yes	No	Tio Down Mat	· -	-				
1000	530	HR-07-10-102	C10	C 10 CORRDIOR	LINK	fail	Mechanical - Damper -	4/11/2019	1010530	Fail 🔻	Yes ,	No	Fire Damper Not Sealed In Fire Compartment	Fire Compartment Compromised	Fire Damper Obstructed				
	531	HR-07-10-103	C10	Outside room HR-07-10-120			Mechanical Damper	4/11/2019	1010531	Fail 🝷	Yes	No		· -	-				
	532	HR-08-10-912	E10	Colleague corridor			Mechanical Damper	4/11/2019	1010532	Pass -	Yes	No		· •	-				
	533	HR-08-10-901	E10	above entrance door			Mechanical Damper	5/11/2019	1010533	Fail 🔻	Yes	No		· -					
	534	HR-08-10-914	E10	Quiet room			Mechanical - Damper	5/11/2019	1010534	Fail 🔻	Yes	No	Fire Damper Not Sealed In Fire Compartment	· -	-				
	535	HR-08-10-919	E10	Sisters Office			Mechanical - Damper	5/11/2019	1010525	Fail 🝷	Yes	No	Fire Compartment Compromised	-	-				
	536	HR-08-10-916	E10	medicine room			Mechanical - Damper	5/11/2019	1010536	Fail 🔻	No	No	Fire Compartment Compromised	-	-				
	537	HR-08-10-902	E10	Male toilet			Mechanical - Damper	5/11/2019	1010537	Fail 🔻	Yes	No	Fire Damper Not Sealed In Fire Compartment	-	-				
	539	HR-08-10-909	E10	Male Changing room			Mechanical 🚽 Damper	5/11/2019	1010539	Faii 🝷	No	Unknown	Fire Damper Not Sealed In Fire Compartment	-	-				
	540	HR-08-10-904	E10	Female toilet changing room			Mechanical - Damper	5/11/2019	1010540	Fail 🝷	No	Unknown	Fire Damper Not Sealed In Fire Compartment	Fire Compartment Compromised	-				
989	541	HR-07-09-312	C9	Above admin room door	LINK	Not Found	Mechanical Damper	5/11/2019	1010541	Fail 🔹	No	Unknown	· ·	· ·	-				
990	542	HR-07-09-312	C9	Above store room HR-07-09-331	LINK	Not Found	Mechanical - Damper -	5/11/2019	1010542	Fail 🔻	No	Unknown	Fire Damper Not Sealed In Fire Compartment		-				

Unique room number. Unique asset number supplied by client.